Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 5/29/2014	Man Days: 1
Inspection Unit: Peoria Persimmon St.	
Location of Audit: Peoria	
Exit Meeting Contact:	
Inspection Type: Standard Inspection - Field Audit	
Pipeline Safety Representative(s): Kevin Hecker	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

CONSTRUCTION INFORMATION			
Location of Construction:	Construction Perf	ormed By:	
800 Block of Ridgemont Drive, Peoria, IL	Ameren Illinois		
Contractor Foreman:	•		
Operator Inspector:			
	Person(s) On Job Site		
Greg Vincent	Bob Hogan	-	
-	-	-	
-	-	-	
-	-	-	

MAIN INSTALLATION		Status
[192.55]	Steel	No
[192.59]	PE	Yes
[192.59]	Other	No
[192.5]	Class location :	Class 3
[192.619,192.621,192.623]	MAOP	60 psig
[192.63]	Pipe Size :	2"
[192.55,192.59]	Specification :	ASTM D-2513

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.55,192.59]	Manufacturer:	Driscoplex
[192.55,192.59]	Pipe Grade :	PE2406/2708
[192.55,192.59]	Wall Thickness :	DR-11
[192.63(a)(2)]	Are pipe, valves, and fittings properly marked for identification?	Satisfactory
[192.227]	Date of Welder qualification:	Not Applicable
General Comment:		
No welding was observed as part of this audit.		
[192.227]	Welder's Name:	Not Applicable
General Comment:		
No welding was observed as part of this audit.		
[192.225,192.275,192.277,192.279,192.283]	Is pipe joined in accordance with approved written procedures?	Satisfactory
[192.285]	Date of Plastic Joining Qualification :	5/21/2013 and 4/24/13
[192.285]	Joiner's name:	Greg Vincent and Bob Hogan (respectively)
[192.455]	Is buried metallic pipe coated?	Not Applicable
General Comment:		
No coated pipe was observed during this audit.		
[192.461]	Does coating meet 192.461?	Not Applicable
General Comment:		
No coated pipe was observed during this audit.		
[192.455(a)(1)]	Is cathodic protection being provided?	Not Applicable
General Comment:		
New main and services were plastic, therefore do not rec	quire CP.	
[192.455(a)(1)]	Is cathodic protection being provided? By Anodes:	No
General Comment:		
New main and services were plastic, therefore do not rec	quire CP.	
[192.455(a)(1)]	Is cathodic protection being provided? By Rectifier:	No
General Comment:		•
New main and services were plastic, therefore do not rec	quire CP.	
[192.461(c)]	Is coating inspected just prior to being installed in the ditch?	Not Applicable

AMEREN ILLINOIS COMPANY/5-29-2014

Page 2 of 5

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
No coated pipe was observed during this au	dit.	
[192.467]	Are pipelines electrically isolated from other underground metallic structures?	Not Applicable
General Comment:		
Newly installed pipeline was PE pipe.		
[192.479]	Are above ground facilities cleaned and coated or jacketed as needed?	Satisfactory
General Comment:		
All meter sets replaced for this project were	new.	
[192.303]	Are comprehensive written construction specifications available and adhered to?	Satisfactory
General Comment:	· .	
Staff reviewed construction plans with Greg plans.	Vincent who did a good job of explaining the long-term plan for the area and how the work ob	served tied into those
[192.305]	Are inspections performed by the operator to check adherence to the construction specifications?	Satisfactory
[192.307]	Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability?	Satisfactory
General Comment:	<u> </u>	
Staff inspected the pipe at several pot holes	while the new main was being pressure tested. No deficiencies were discovered.	
[192.319]	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Not Checked
General Comment:	<u> </u>	
Staff was not present at the time the pot hole	es were backfilled.	
[192.321(c)]	Is plastic pipe installed as to minimize shear and tensile forces?	Satisfactory
[192.321(e)]	Does plastic pipe have means of locating while underground?	Satisfactory
General Comment:		
Staff observed tracer wire bored with the 2"	PE pipe.	
[192.325]	Are required clearances from underground structures being maintained?	Satisfactory
[192.327]	Is required cover being obtained appropriate to type of pipeline and location?	Satisfactory
General Comment:	<u> </u>	
Staff checked clearance at several pot holes	s with depth ranging from 20-28".	
[192.503]	Are general testing requirements being met?	Satisfactory
AMEREN II I INOIS COMPANY/5-29-2014		Page 3 of F

AMEREN ILLINOIS COMPANY/5-29-2014

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.517]	Are records being made of strength and leak tests?	Satisfactory
[192.807]	Were covered employees Operator Qualification records reviewed to ensure qualification?	Satisfactory
General Comment:	·	
Staff reviewed the qualification for Ga	ry Vincent and Bob Hogan.	
[192.805(c)]	Were non-qualified personnel being "directed and observed" by a qualified individual?	Satisfactory
General Comment:	·	
There was one apprentice on the job	site being observed by 2 qualified individuals.	
[192.805(c)]	Were span of control limitations being followed?	Satisfactory
General Comment:	·	
There was one apprentice on the job	site being observed by 2 qualified individuals.	
Was a Protocol 9 (Form 15) C	ompleted?	No
[192.614]	Were One Call Notifications performed as required?	Satisfactory
[192.614]	Dig Ticket #	Not Checked

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

AMEREN ILLINOIS COMPANY/5-29-2014